

Applicant : Shandong Deli Aluminium Technology Co., Ltd.
Address : No.139, Daixi Sixth Road, Gaoxin Subdistrict Office, Zouping, Binzhou, Shandong
Client No. : 05438716
Manufacturer : Shandong Deli Aluminium Technology Co., Ltd.
Address : No.139, Daixi Sixth Road, Gaoxin Subdistrict Office, Zouping, Binzhou, Shandong

Report on the submitted sample said to be

Sample Name : ALUMINIUM FOIL
Model No. : --
Sample Model : --
Sample Received Date : Jun. 18, 2019
Sample Tested Date : Jun. 18-25, 2019
Test Requested : As specified by client, to determine the Bisphenol A content in the submitted samples
Test Result(s) : Please refer to the following page(s).



Company No.07113834

Signed for and on behalf of
Beide (Shenzhen) Product Service Limited

Written by :

Anna Deng

Anna Deng

Inspected by:

Austin Zhong

Austin Zhong

Approved by:

Martin Wang

Martin Wang



This report is considered invalidated without the Special Seal for Inspection of the Beide (Shenzhen) Product Service Limited, This report shall not be altered, increased or deleted. The results shown in this test report refer only to the sample(s) tested. Without written approval of Beide (Shenzhen) Product Service Limited, this test report shall not be copied except in full and published as advertisement.

Report No. : B-R190624145

Test Results:

Test method: with reference to US EPA 3550C:2007, analysis was performed by Liquid Chromatograph Mass Spectrometer (LC-MS)

| Test item | Unit | Result | MDL |
|-------------------|-------|--------|-----|
| Bisphenol A (BPA) | mg/kg | N.D. | 0.1 |


Note:

1. mg/kg = milligram per kilogram.
2. MDL= Method Detection Limit.
3. N.D.= Not Detected (<MDL)



This report is considered invalidated without the Special Seal for Inspection of the Beide (Shenzhen) Product Service Limited, This report shall not be altered, increased or deleted. The results shown in this test report refer only to the sample(s) tested. Without written approval of Beide (Shenzhen) Product Service Limited, this test report shall not be copied except in full and published as advertisement.

Photos of the sample



*** End of report ***

This report is considered invalidated without the Special Seal for Inspection of the Beide (Shenzhen) Product Service Limited, This report shall not be altered, increased or deleted. The results shown in this test report refer only to the sample(s) tested. Without written approval of Beide (Shenzhen) Product Service Limited, this test report shall not be copied except in full and published as advertisement.